

Heavy Equipment

Inspection Date Aug 16, 2019 5:27 pm CDT

Job # NA 2016 5689

Ordered Aug 12, 2019 3:04 pm CDT

Delivered Aug 16, 2019 5:42 pm CDT

Country US



Order Information

Asset ID

not provided

Location

90 Chestnut Street
Murray, KY 42071

Equipment Details

VIN (Driver Side Door)

1FUJGLDVXELFP5103

Year

2014

Make

Freightliner

Model

Cascadia 125

Mileage

633377

Videos

Heavy Equipment

Inspection Date Aug 16, 2019 5:27 pm CDT

Job # NA 2016 5689

Ordered Aug 12, 2019 3:04 pm CDT

Delivered Aug 16, 2019 5:42 pm CDT

Country US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Heavy Equipment

Inspection Date Aug 16, 2019 5:27 pm CDT

Job # NA 2016 5689

Ordered Aug 12, 2019 3:04 pm CDT

Delivered Aug 16, 2019 5:42 pm CDT

Country US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Exterior Damage Photos

Heavy Equipment


Inspection Date Aug 16, 2019 5:27 pm CDT

Job # NA 2016 5689

Ordered Aug 12, 2019 3:04 pm CDT

Delivered Aug 16, 2019 5:42 pm CDT


Country US



Dent and scratch in paint on the passenger side sleeper



Scuff marks on the passenger side mirror



Paint scratched on passenger side by right head light



Paint off and scratch in drivers mirror

Media - Interior Condition Photos

Heavy Equipment

Inspection Date Aug 16, 2019 5:27 pm CDT

Job # NA 2016 5689

Ordered Aug 12, 2019 3:04 pm CDT

Delivered Aug 16, 2019 5:42 pm CDT

Country US




Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)



Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

Media - Interior Damage Photos

Heavy Equipment

Inspection Date Aug 16, 2019 5:27 pm CDT

Job # NA 2016 5689

Ordered Aug 12, 2019 3:04 pm CDT

Delivered Aug 16, 2019 5:42 pm CDT

Country US



Dirty spot on roof



Scuffs on dash board



Floors look perfect

Operating Condition

What is the condition of the Interior?

Good

Are there any tears in the upholstery?

One or a few small tears

Are there any strange odors in the vehicle? If so, provide a short description

The agent did not observe any strange odors in the vehicle

Is there any missing equipment (ie lights etc)? If so, provide details

The agent did not observe any missing equipment.